Part-1

Performa for the Safety School Building (To be filled by the Head of School/ Institute)

- 1	4	The state of the s	willing to line to lit of the Dulling Sa Sel
1.	Name of Sch	ool :	mi Guri Maryobind Sahib Public 8250
2.	Location		and the ladded was
3.	Plot Area	:7:7.	000 year 1 (176954H)
4.	Plinth Area		rosg years (3600 (4)
5.	Number of S		& Stery.
6.	Year of Construction of Building : 1999, 1992		
2. 3. 4. 5. 6. 7.	Supervision of the qualified Engineer,		
	The following details may be given :		
	a)	Name of the Engineer :	P. Amargent Sigh. Took consellering
	b)	Address :/	381/L Lashiana
	c) -	Set of Structure Drawing used in the	
		Construction if available :	Two New Drawing Sel.
	d)	Name of the Architect :	athbis Sirgh
8.	Whether the building has been constructed for the purpose of:		
	a)	School	(Yes No) JES
	b)	Residential purpose and converted	(Yes/No)
		for use as a school	
9.	Materials used for Roof:		
	a)	R.C.C Slabs	(Yes/No) //C (Yes/No) //C
	b)	R.S. Joists and Battens	(Yes/ No) 2022
	c)	Wooden Joists and Battens	(Yes/ No)//
10.	Materials used for walls:		
	a)	Mud Mortar	Yes No. No
	b)	Cement Mortar	2 (Yes No)
	c)	Plaster (i) Lime Mortar	V(Yes' No) yes
		(ii) Cement Mortar	V(Yes' No)
11.	Flooring:		
	a)	Conglomerate	Wies No) 425
	b)	Terrazzo	(Yes/No)
	c)	Brick Paying	(Yes/No)
	Detailed I	Prawing indicating dimensions	
	of the rooms along with size and location of doors and windows		populus.
	or doors a	na willadwa	
			A.
		1	O I I I Trust

SHRI GURU HARGOBIND SAHIB
PUBLIC SR. SEC. SCHOOL,
Giaspura, P.O. Dhandari Kalan, Ludhiana.

Signature with stand of horizontal Stand Cappers, P.O. District Research

Part-II (To be filled by S.D.E of P.W.D B&R Department) Building Safety Report

Name of School: Short Cause Harfabired Sahib Public So See School Garling

I have visited the above mentioned School building along with Sh.

Profiles Site on dated selection and have visually inspected. It seems visually safe subject to the following observation & conditions

- a. Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details Structural Drawings, Technical Specifications, Test Reports of Material used Quality Control reports and Certificate from Engineer in Charge for Construction are not available.
- b. In case of any addition, alteration of expansion and modification of this building are done; certificate may be re-obtained after completion from undersigned.
- c. In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d. A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- A separate certificate regard Electrical Work should be obtained from the competent authority.
- f. The owner of the building/Management is fully responsible regarding safety of building from all angels in spite of this report,
- g. The covered area of the building is
- h. This report is not valid for legal purpose.
- i. As per Government order no. 5/13/2018-3BR3/1294287/3 dated 10-08-2018 for issue of building safety certificate Para 2.0 (a), this certificate as requested by school authority is issued for period of 6/4 years up to 3/103/2028

Junor Engineer

ENSSANO 25

vale 12/04/241

Aub Divisional Engineer Provincial Sub Division No.2 PWD BER, Ludhiana.

ericuser. 2014 : Oscardingun datu, (1984) 2014 : Edit S. 235 : 25 N. Delin 2014 : Edit S. Patensel (1984) (1984)

Principal Simi Gunu Harbushin Samu Pushic Sr. Sechudi Marana, P.O. Dherdod Kalan, Indus