

## Part :- I

### Proforma for the Building Safety Certificate

(To be filled by Head of the School / Institute)

1. Name of the building:- Shri Gurus Hargobind Sahib Public Sem. Sec. School
2. Location :- Gasapura, Ludhiana
3. Plot area:- :- 7500 sq. yard ( 67500 sq. ft)
4. Plinth Area:- :- 4000 sq. yard (36000 sq. ft)
5. Number of stories:- :- Two storeys
6. Year of construction of building:- :- 1992, 1999
7. Supervision of the qualified engineer the following details may be given
- A. Name of the engineer :- ER Amarjeet Singh Circuit House Road
- B. Address:- 1881/ R Ludhiana
- C. Set of structure drawing used  
in the construction if available Two No's Drawing Set
- D. Name of the architect:- Lakshbir Singh
8. Whether the building has been constructed for the purpose of:-
- A. School (Yes / No)..... Yes
- B. Residential purpose and converter (Yes / No)..... No  
for use as a school
9. Materials used for roof :-
- A. R.C.C. slaps (Yes / No)..... Yes
- B. RS joists and Battens (Yes / No)..... No
- C. Wooden Joists and Battens (Yes / No)..... No
10. Materials used for walls
- A. Mud mortar (Yes / No)..... No
- B. Cement mortar (Yes / No)..... Yes
- C. Plaster 1. lime mortar (Yes / No)..... Yes  
2. Cement mortar (Yes / No)..... Yes
11. Flooring
- A. Conglomerate (Yes / No)..... Yes
- B. Terrazzo (Yes / No)..... No
- C. Brick paving (Yes / No)..... No
12. Detailed drawing indicating dimension of the rooms along with the size and location of doors and windows. Attached

Signature with stamp of Bhupinder Singh Principal  
SHRI GURU HARGOBIND SAHIB  
PUBLIC SR. SEC. SCHOOL,  
Gasapura, P.O. Dhanderi Kalan, Ludhiana.



No 148

Date. 16-04-2026

**Part 2**

**To be filled by S.D.E. of P.W.D. B&R department  
Building Safety Report**

Name of the school :- Shri Guru Margobind Sahib Public Sen Sec School.  
Giorpur Lohi.

I have visited the above-mentioned school building along with  
Sh. Jasne Singh J.E. on dated 10/4/26 and have visually inspected. It seems usually safe  
subject to the following observations and conditions.

- A. Parameter to check the stability and safety of building such as architectural drawings bearing capacity foundation details structural drawings technical specification test reports of material used quality control reports and certificate from engineer in charge for construction are not available.
- B. In case of any addition alteration of expansion and modification of the building are done certificate may be re obtained after completion from undersigned.
- C. In case of building is affected by flood or if there is settlement of walls foundation of sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- D. A separate certificate regarding firefighting should be obtained from the competent authority
- E. A separate certificate regarding electrical work should be obtained from the competent authority
- F. The owner of the building management is fully responsible regarding safety of building from the angles in spite of the report
- G. The covered area of the building is 36000 Sqft.
- H. This report is not valid for legal purpose
- I. As per government order number No. 5/13/2018-3BR3/1294287/3 dated 10-08-2018 for issue of building safety certificate para 2.0(A), this certificate as requested by School authority issued for period of 05 Years up to 31/03/2031 (month 2031)

  
Junior Engineer

  
**Sub Divisional Engineer**  
**Construction Sub Division**  
**PWD B & R, Ludhiana**